


6010 Teleworker Solution - Configuration 2



The following are required to implement the solution:

- Head office requires a server installed with the 6000 MAS software and the Teleworker Gateway blade.
- Head office requires Internet bandwidth sufficient to support the required number of teleworkers (approximately 50 kbps per teleworker if G.729 compression is enabled).
- Head office requires a static IP address.
- Each remote site requires a 5220 IP Phone with phone load 5.19 or later.
- Each remote site requires a DSL/cable router providing Network Address Translation (NAT) and local DHCP.
- Each remote site requires broadband connectivity (static IP address not required).

Note: For detailed configuration requirements please refer to the 6010 Teleworker Solution Engineering Guidelines – DK111362. Available on Mitel OnLine.